

SBS-DAQ-GMn-HCal - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
618	Feature	New	Normal	Re-configure F1 clock to use TI clock		03/29/2021 04:16 PM
617	Feature	New	Normal	Re-configure F1 clock to use TI clock		03/29/2021 07:53 PM
593	Bug	New	Normal	HCAL Pulser state readout not properly read out in CODA3 ROL	Juan Carlos Cornejo	09/18/2020 11:20 AM