

## SBS-DAQ-GMn - Issues

| #   | Tracker | Status      | Priority | Subject                                                      | Assignee            | Updated             |
|-----|---------|-------------|----------|--------------------------------------------------------------|---------------------|---------------------|
| 651 | Task    | New         | Normal   | BPM/Raster weldment                                          |                     | 07/15/2021 08:50 PM |
| 650 | Task    | New         | Normal   | Install 1 more VXS crate weldment                            |                     | 07/15/2021 08:50 PM |
| 649 | Task    | New         | Normal   | Router installation                                          |                     | 07/15/2021 08:44 PM |
| 619 | Bug     | New         | Normal   | Scalers rate for triggers                                    |                     | 05/27/2021 01:42 PM |
| 618 | Feature | New         | Normal   | Re-configure F1 clock to use T1 clock                        |                     | 03/29/2021 04:16 PM |
| 617 | Feature | New         | Normal   | Re-configure F1 clock to use T1 clock                        |                     | 03/29/2021 07:53 PM |
| 598 | Bug     | New         | Normal   | Read out error with crate1 MPD12                             |                     | 10/23/2020 10:24 AM |
| 597 | Bug     | New         | Normal   | Read out error with crate0 MPD14                             |                     | 10/23/2020 10:24 AM |
| 593 | Bug     | New         | Normal   | HCAL Pulser state readout not properly read out in CODA3 ROL | Juan Carlos Cornejo | 09/18/2020 11:20 AM |
| 592 | Task    | New         | Normal   | Setup gate from TS                                           |                     | 09/18/2020 09:44 AM |
| 587 | Task    | In Progress | Normal   | VETROC order                                                 | Alexandre Camsonne  | 10/23/2020 10:29 AM |
| 584 | Bug     | New         | Normal   | FADC scalers readout                                         |                     | 09/11/2020 11:31 AM |
| 583 | Task    | New         | Normal   | Send common noise zero supression code to Paolo              | Ben Raydo           | 09/11/2020 10:56 AM |
| 582 | Task    | New         | Normal   | Detector cabling                                             |                     | 09/11/2020 10:45 AM |
| 581 | Task    | New         | Normal   | Detector cabling layout                                      |                     | 09/11/2020 10:44 AM |
| 580 | Task    | New         | Normal   | ADC setup                                                    |                     | 09/11/2020 10:44 AM |
| 579 | Task    | New         | Normal   | Setup TS crate                                               |                     | 09/18/2020 09:44 AM |
| 578 | Bug     | New         | Normal   | Install CODA3 for CDet                                       | David Flay          | 09/11/2020 10:36 AM |
| 577 | Task    | New         | Normal   | VXS VETROC setup                                             |                     | 09/11/2020 10:35 AM |
| 576 | Task    | New         | Normal   | BigBite GEM readout setup                                    |                     | 09/11/2020 10:21 AM |
| 575 | Task    | New         | Normal   | INFN cleanroom optical                                       |                     | 09/11/2020 10:21 AM |
| 393 | Task    | New         | Normal   | Hodoscope Electronics                                        |                     | 07/21/2018 03:17 PM |